

## SilverStorm™ 9000

QLogic Corporation  
All rights reserved

### Table of Contents

<a href="#">1</a>	<a href="#">Version</a>
<a href="#">2</a>	<a href="#">Changes</a>
<a href="#">3</a>	<a href="#">Bug Fixes</a>
<a href="#">4</a>	<a href="#">Known Issues</a>
<a href="#">5</a>	<a href="#">Additional Information</a>
	<a href="#">5.1</a> <a href="#">Included in this release:</a>
	<a href="#">5.2</a> <a href="#">Miscellaneous:</a>
<a href="#">6</a>	<a href="#">Trademarks</a>
<a href="#">7</a>	<a href="#">Notices</a>
<a href="#">8</a>	<a href="#">Contacting Support</a>

## 1 Version

---

These release notes describe the changes, fixes, known issues, and release details that apply to the SilverStorm 9000 switches, firmware version 4.2.5.5.1.

## 2 Changes

---

The following changes and fixes have been made between versions 4.2.5.3.2 and 4.2.5.5.1.

### Hardware Support

None

### OS Support

None

### Software Components

- ◆ A license key is no longer required in order to run the Embedded Subnet Manager (ESM).

## Industry Standards Compliance

N/A

### 3 Bug Fixes

---

The following fixes have been made between versions 4.2.5.3.2 and 4.2.5.5.1:

- ◆ 9000 Series Common:
  - None.
- ◆ 9024CU Specific:
  - None.
- ◆ 9020 Specific:
  - None.
- ◆ 9040 Specific:
  - None.
- ◆ 9080 Specific:
  - None.
- ◆ 9120 Specific:
  - None.
- ◆ 9240 Specific:
  - None.
- ◆ Miscellaneous:
  - None.

The following fixes have been made between versions 4.2.5.2.1 and 4.2.5.3.2:

- ◆ 9000 Series Common:
  - Fixed SSH performance issues.
  - There is no longer a subnet manager (SM) memory leak on the second sweep of a fabric.
  - Performing a 'capture' on a switch running the master embedded subnet manager no longer causes subnet manager timeouts and failover.
- ◆ 9024CU Specific:
  - None.
- ◆ 9020 Specific:
  - None.
- ◆ 9040 Specific:
  - None.
- ◆ 9080 Specific:
  - None.
- ◆ 9120 Specific:
  - None.
- ◆ 9240 Specific:
  - None.
- ◆ Miscellaneous:
  - None.

## 4 Known Issues

---

Known Issue	Workaround
<p>(9000 Common) If thresholds for symbol errors have been set (ismSetPStatThresh) and a host directly-attached to the switch is rebooted, the user will see a message similar to the following in the switch log:</p> <pre>MasterSpine1-&gt; W 2006/07/11 13:47:29.640D: Thread "ibStatThr" (0x868a3d80)  TMS: Infiniband Error Statistic Overlimit: icsIBStatMib: portSymbolErr Port name: L04P03 Id  : 0 Rate: 65535 Threshold: 1  W 2006/07/11 13:47:30.640D: Thread "ibStatThr" (0x868a3d80)</pre>	<p>None. These errors can be safely ignored.</p>

## 5 Additional Information ]

---

### 5.1 Included in this release:

---

SilverStorm 9000 Firmware version 4.2.5.5.1 for the following switches:

- ◆ SilverStorm 9024CU
- ◆ SilverStorm 9020
- ◆ SilverStorm 9040
- ◆ SilverStorm 9080
- ◆ SilverStorm 9120
- ◆ SilverStorm 9240

**NOTE:** SilverStorm 9000 BootRom version 3.3.0.0.12 or greater is supported.

### 5.2 Miscellaneous:

---

- ◆ Due to changes in the 4.2 switch chip firmware, when upgrading from a previous release it will take up to 8 minutes to update a fully-populated 9120 chassis (or 9240 hemisphere) when upgrading from a 4.1 or 4.0 level of firmware.
- ◆ If there are dual managed spines in a chassis, this release must be placed on both spines as the inactive image. Both spines must then be set to boot into this image. Once complete, reboot both spines. This will be a disruptive reboot. It is recommended to always have both spines running the same version of firmware.

## 6 Trademarks

---

Accelera, Accelerating Cluster Performance, FastFabric, InfiniCon Systems, InfiniNIC, InfiniPath, InfiniView, Intelligent NIC, Networking University, NetXen, QLogic, the QLogic logo, ReadyPath, SANdoctor, SANSurfer, and SilverStorm are registered trademarks of QLogic Corporation.

To the extent a name or logo does not appear on this list does not constitute a waiver of any and all intellectual property rights that QLogic Corporation or its subsidiaries has established in any of its product, feature, or service names or logos. All other brand and product names are trademarks or registered trademarks of their respective owners.

## 7 Notices

---

Information furnished in this document is believed to be accurate and reliable. However, QLogic Corporation assumes no responsibility for its use, nor for any infringements of patents or other rights of third parties which may result from its use. QLogic Corporation reserves the right to change product specifications at any time without notice. Applications described in this document for any of these products are only for illustrative purposes. QLogic Corporation makes no representation nor warranty that such applications are suitable for the specified use without further testing or modification. QLogic Corporation assumes no responsibility for any errors that may appear in this document.

## 8 Contacting Support

---

Please feel free to contact your QLogic approved reseller or QLogic Technical Support at any phase of integration for assistance. QLogic Technical Support can be reached by the following methods:

Web: <http://support.qlogic.com>

E-mail: [support@qlogic.com](mailto:support@qlogic.com)

[Go to Top](#)



© Copyright 2012. All rights reserved worldwide. QLogic, the QLogic logo, and the Powered by QLogic logo are registered trademarks of QLogic Corporation. InfiniBand is registered trademark of the InfiniBand Trade Association (IBTA). All other brand and product names are trademarks or registered trademarks of their respective owners.